



M25 Sphere – Area 5
Environmental Amenity Index



Route Inspected
Description of Area
Date of Inspection
Names of Attendees

M4 A track MP1771
verge
5th July 2005



EAI01 – Amount of Litter and Debris												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	B	B	B	B	B	B	B	B	C	B	B	63
Description and Comments: Litter levels generally negligible – except 22/1 on MSA onslip												

EAI02 – Standard of Grass Cutting												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	B	B	C	C	B	B	C	B	C	B	A	57
Description and Comments: 17/6 – standard of grass cutting improved												

EAI03 – Standard of Grass Cutting at Obstructions												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	A	A	A	B	B	B	C	B	B	B	B	72
Description and Comments:												

M25 Sphere – Area 5
Environmental Amenity Index



Route Inspected
Description of Area
Date of Inspection
Names of Attendees

M4 A track MP17/1
verge
5th July 2005



EAI04 – Weed Growth In Verges and Central Reserve												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	B	B	C	C	B	B	C	B	C	B	B	54
Description and Comments: Weed growth variable, generally not bad in most areas 17/6 – weed growth not as bad 19/1 – weeds bad in central reserve 21/1 – hogweed & knotweed needs treating in this section												

EAI05 – Weed Growth in Gullies and Drainage												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	A	A	A	A	A	A	A	A	A	A	A	100
Description and Comments: No impairment to function anywhere												

EAI06 – Visibility of Signs												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	A	A	A	B	A	A	A	B	C	A	B	82
Description and Comments: 17/6 – slight obscuration by overhanging fringe 20/5 – slight obscuration by vegetation on the approach 21/1 – obscuration of 100m sign 20/6 – marker post broken												

M25 Sphere – Area 5 Environmental Amenity Index

Route Inspected
Description of Area
Date of Inspection
Names of Attendees

M4 A track MP17/1
verge
5th July 2005



EAI07 – Cleanliness of Signs (Daytime during BST, Night time during GMT)												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	A	A	A	A	A	A	A	A	A	A	A	100
Description and Comments:												

EAI08 – Sweeping of Channels – Accumulation of Silt and Detritus												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	B	B	B	B	B	B	B	B	B	B	B	66
Description and Comments: Cyclic sweeping due in next fortnight												

EAI09 – Accumulation of Vegetation on/ over Carriageway, Footways, Cycleways & Bridleways												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	A	A	A	A	A	A	A	A	A	A	A	100
Description and Comments: 19/6 – be aware of overhanging branches – not yet significantly overhanging. Consider proactive pruning. 21/1 – consider proactive pruning to overhanging branches 21/0 – overhanging ash needs attention												

M25 Sphere – Area 5 Environmental Amenity Index

Route Inspected
Description of Area
Date of Inspection
Names of Attendees

M4 A track MP17/1
verge
5th July 2005




EAI10 – Illegal Signs, Obstructions and Graffiti on HA Structures												
Measured against EPA Code of Practice and Photographs												
Survey Point	0	500	1000	1500	2000	2500	3000	3500	4000	4500	5000	Average
EPA Grade	A	A	A	A	A	A	A	A	A	A	A	100
Description and Comments:												

Signed on behalf of the HA	Print Name	Date

Signed on behalf of Mouchel	Print Name	Date

Signed on behalf of Carillion	Print Name	Date

Once completed this report should be forwarded to  the Highways Agency, the corresponding Mouchel Route Manager and the KPI Co-ordinator for Mouchel at Scratchwood.